

BEFORE



DURING



**1 FILLED THE HOLE WITH CRUSHED
DECOMPOSED GRANITE (DG) - LEFT
2 REPAIRED TREAD ON RIGHT**

AFTER*



**WE PUT A FINAL LAYER OF DIRT ON
THE DG**

BEFORE



AFTER



BEFORE



AFTER



BEFORE



DURING



AFTER



**FORMER TRAIL ROUTE
FACING EAST**



**RUT FEEDING HEADCUT
FACING WEST**



HEADCUT

